

for our files

Montgomery Co.
HEALTH DISTRICT

Name of Landfill South Dayton Dump and Landfill Location 1975 Springboro Rd.
 Name of Operator Mr. Aline Brillant Address 2768 Kreitzger Rd.
 Method of Operation - Trench _____ Area X Other _____
 Estimated Daily Receipts - Loads 35 Tons _____ Cubic Yards _____
 Area of Landfill - Total Acres 45 Acres Filled _____ Estimated Remaining Life _____ Yr
 General Characteristics of Site - Quarry _____ Borrow Pit _____
 Gravel Pit X Strip Mine _____ Gully _____ Hillside _____
 Level Area _____ Marsh or Flood Plain _____ Other _____
 Hours of Operations 7:00 A.M. To 5:00 P.M. Days operated per week 6
 Geographic Area Served Montgomery Co. Population Served 800,000
 License Number none Salvaging Permitted - Yes X No _____

Items marked by (X) are in violation.

I. SITE - HE-24-04

Ground Water Protection _____
 Surface Runoff _____
 Leachate Runoff _____
 Solid Waste in Water Course _____
 Dust Control _____
 Odor Control _____
 Smoke Control _____

IV. OPERATION - HE-24-09

(a) Operated According to Plan X
 (b) Access to Site Limited _____
 (c) Dumping Area Restricted _____
 (d) Blowing Paper & Debris _____
 (e) Equipment Adequate _____
 (f) Equipment Repair _____
 (g) Properly Spread _____
 (h) Properly Compacted X
 (i) Covered Material Adequate X
 (j) Covered Daily X
 (k) Finished Cover Adequate _____
 (l) Finished Grade Adequate _____
 (m) Special Material Handling _____

(i) Vector Control
 General Operation _____
 Supplemental Control _____
 (j) Salvaging _____
 (k) Animals Excluded _____
 (l) Fire Protection _____
 (m) Hot or Burning Loads _____
 (n) Records X
 (o) Responsible Party Present _____

II. DUMPING & BURNING - HE-24-06

Open Dumping X
 Open Burning X

III. APPROVALS

Site - HE-24-07 _____
 Plan - HE-24-08 _____

Sewage Solids _____
 Sewage Liquids _____
 Hazardous Substances _____

COMMENTS AND RECOMMENDATIONS:

II HE-24-06 (b) Open burning is not permitted on a landfill site. Open burning was observed on this day.
 IV HE-24-09 (a) The landfill is not being operated according to an operational procedure plan, since we have none on file.
 IV HE-24-09 (e) Material is not being properly compacted.
 (f) The exposed refuse materials are not being covered daily with at least 6" of fill material on a daily basis. Solid wastes are laying exposed on the surface of the ground.
 (m) We have no current records of your daily log of operation for 1970.

3-17-70

Date

Dale E. Alexander

Sanitarian